Heartland Plating Administrative Record Photo Log

Photo	Date	Photographer	Direction	Description
Number				
P1010043	7/23/13	Ruiz	North	Drums marked HazMat on dock
P1010046	7/23/13	Ruiz	North	Drums marked HazWaste at the rear of the warehouse
P1010047	7/23/13	Ruiz	North	Corrosive Totes at the rear of the warehouse
P1010050	7/23/13	Ruiz	East	Open hole where vent fan was previously positioned
P1010057	7/23/13	Ruiz	North	Totes staged at the warehouse
P1010058	7/23/13	Ruiz	South	Small Containers staged by pH
P1010059	7/23/13	Ruiz	East	Small Containers staged by pH
P1010062	7/23/13	Ruiz	South	Drums staged according to pH
P1010063	7/23/13	Ruiz	South	Drums staged according to pH
P1010064	7/23/13	Ruiz	East	Drums staged according to pH
P1010065	7/23/13	Ruiz	East	Cylinders staged at the rear of the warehouse
P1010066	7/23/13	Ruiz	West	Plating tanks
P1010067	7/23/13	Ruiz	West	Entrance to office from Plating Line area

B780



2.0

























